



Green Tomato Property Damage Assessment

Location:

4910 & 4912 St. Elmo Avenue
Bethesda, Maryland

Client: Green Tomato LLC c/o Greenhill Capital Corporation

Description:

- Review of consulting engineers' reports & findings
- Coordination with Owner's Legal Counsel
- Coordination with Owner's Property Management
- Obtain Selective Demolition Permits
- Administer Selective Demolition Contractor Operations
- Make findings and recommendations to Owner
- Red Tomato Building Conditions
- BCC Auto Building Conditions </

Project Team:

- Consulting Structural Engineer: Rogan Stearns PE, Stearns Engineering
- Consulting Geotechnical Engineer: Gerry Davit PE, Professional Consulting Corp.
- Consulting Construction Cost Estimator: Sigal Construction
- Legal: Venable LLP

Completion Date: January 2015

